Franklin Road Qualitative Assessment Summary

The design options are compared to the current state of Franklin Road and rated in terms of the degree of improvement each option provides.

Degree of Improvement Rating Scale

Rating	+2	+1	0	-1	-2
Degree of improvement	Major better	Minor better	Same	Minor worse	Major worse

					Options				
Criteria	Description	Do min	A (1)	Am (2)	В	С	D	E (3)	
Walking									
Walking Safety	Pedestrian safety walking across the road or along the paths	0.5	1.0	0.5	-0.5	-2.0	-1.5.	0.5	
Walking Amenity	How good is the walking experience?	0.5	0.5	0.5	0.0	-1.0	-0.5	1.0	
Cycling									
Cycling Confident	A facility that would encourage confident cyclists to use it.	0.0	1.5	2.0	1.0	-1.0	-1.0	-1.0	
Cycling Non- Confident	A facility that would encourage non - confident cyclists to use it.	0.0	1.0	1.5	1.0	1.0	1.0	1.5	
Cycling Safety	Cyclists can travel along and across Franklin Rd with a high degree of safety at all times	0.0	1.5	2.0	1.0	0.5	1.0	0.5	
Road Safety									
Right turns	The ability to turn into properties safely	0.0	0.0	-0.5	0.0	0.0	0.0	-0.5	
Traffic Speed	Facilities to encourage slower speeds along the road and potentially less severe crashes	0.0	1.0	2.0	0.5	-0.5	-0.5	2.0	
Resident Driveway	A facility that enables safe passage in and out of a property especially reversing out	0.5	1.0	1.5	1.5	1.0	1.0	1.5	
Others Facilities									
Parking	Vehicles can park with ease and there are sufficient spaces to suit residents needs	-1.0	-1.0	-1.0	-1.0	-1.0	-1.0	-1.5	
Tree Impact / Health	The impact on the trees health is not compromised	0.0	1.5	1.5	1.5	1.5	1.5	2.0	
Public Realm									
Sense of place	The design and detail of a street is sympathetic to the local Character	0.0	-0.5	0.5	-1.0	-0.5	0.0	1.5	
Place and movement balance	Capacity for other uses E.g. Christmas lights	0.0	0.0	1.0	0.0	-0.5	-0.5	2.0	
		0.5	7.5	11.5	4.0	-2.5	-0.5	9.5	